## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 72\$43750003

BRIDGE OWNER: STATE OF TENNESSEE ROAD NAME: CRANMORE COVE RD

CROSSING: SALE CREEK

LATITUDE:: N 35.47674 DEGREES
LONGITUDE: W 85.07267 DEGREES

COUNTY: RHEA
ROUTE: SR303
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.94
YEAR BIJLE: 1960

LON	NGHODE. W 65.07207 DEGREES	TEAN BOILT. 1900	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	FEEL PILE FOUNDATION	
BENTS:	STEEL PILE BENT ON PILE FOUND	TION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Dridge is see	our critical: bridge foundations de	remined to be unstable for calculated scour conditions. Rip-rap protection	
	stalled and is in good condition.	ermined to be unstable for calculated scour conditions. Rip-rap protection	
		INSPECTION PROCEDURES ————————————————————————————————————	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
1. C 2. C [ ] - Chec [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	along curb line, both bridge rails and outer edge of bridge deck. ts.	
lf Closure is	recommended:		
Coun temp	nty or City Maintenance Persor	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offici		District maintenance or local highway maintenance ge on the selected detour route shall be checked	
[ ] - The bunits	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONT	ACT PERSONNEL:	TELEPHONE NUMBER:	
REGIO	ON BRIDGE ENGINEER	(423) 290-7467	
DISTR	ICT MAINTENANCE SUPERVISOR	(423) 290-7491	
TENNI	ESSEE HIGHWAY PATROL	(423) 634-6898	
The re	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS	:		
Latest Bridg	List of Equipment to conduct the Inspection ge Inspection Report Report with the above Checklist ign Plans, if available	<u>n:</u>	
	ure with weight		
Plumb bob			
Range Pole			
A 1000 Foo	t Roll of yellow Polyethylene Barricade Tap	e printed with the following message:	
	CVEELA HY2VDU REED V	WΔV	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24