HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 74S62800003

BRIDGE OWNER: ROBERTSON COUNTY
ROAD NAME: SANDY SPRINGS RD
CROSSING: MILLERS CREEK

LATITUDE:: N 36.44777 DEGREES LONGITUDE: W 87.00985 DEGREES

COUNTY: ROBERTSON
ROUTE: 01958
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.20
YEAR BUILT: 1974

		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON CONCRETE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	I CONCRETE SPREAD FOOTING FOUNDATION	
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		- INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	-	[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	on along curb line, both bridge rails and outer edge of bridge deck. nts.	
If Closure is	recommended:		
Coun temp] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.		
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)	
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	e Engineer	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any be prior to signing the detour route.	ridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructurally stable.		
<u>0</u>	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
C	COUNTY MAYOR'S OFFICE	(615) 384-2476	
H	HWY. CHIEF ADMINISTRATOR'S OFFICE	(615) 384-2507	
C	COUNTY SHERIFF'S OFFICE	(615) 384-7971	
a s			
Sugges	sted List of Equipment to conduct the Inspec	tion:	
Latest	Bridge Inspection Report		
Scour I	POA Report with the above Checklist		
Bridge	Design Plans, if available		
•	neasure with weight		
Plumb			
Range			
A 1000	Foot Roll of yellow Polyethylene Barricade T		
	SAFETY HAZARD KEEF	PAWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)