## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: ROBERTSON

BRIDGE ID NUMBER: 74S62820007

BRIDGE OWNER: ROBERTSON COUNTY
ROAD NAME: CROSS PLAINS RD
CROSSING: HONEY RUN CREEK
LATITUDE:: N 36.54168 DEGREES
LONGITUDE: W 86.70395 DEGREES

ROUTE: 01021
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 9.15
YEAR BUILT: 1977

		TYPE OF SUPE	RSTRUCTURE =		
MAIN SPAN:	PRESTRESSED CONCRETE CONTIL STRINGER/MULTI-BEAM OR GIRDE	NUOUS -	APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUE	STRUCTURE -		
ABUTMENTS:	S: CONCRETE SPILL THROUGH ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION				
BENTS:	ENTS: NOT APPLICABLE				
PIERS:	CONCRETE HAMMERHEAD PIER ON CONCRETE SPREAD FOOTING FOUNDATION				
		SCOUR EV	ALUATION =		
	nknown foundations. Risk of sco cant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.	
		- INSPECTION F	ROCEDURES -		
What Initiated the Call-out Inspection?		[ ] Bridge	Watch Alert		
		[ ] TDOT	District or Loca	Il Maintenance Personnel	
		[ ] THP o	r Local Law Enf	forcement Personnel	
		[ ] Other:			
[ ] - Span 1. C 2. C [ ] - Checl [ ] - Checl [ ] - Revie	check for plumb of piers or being the for embankment erosion the for drift build-up on piers or the pier exposure, if possible, ar the latest bridge inspection	ell as verticall n along curb l nts. bents nd compare to	ine, both bridge		
if Closure is	recommended:				
Coun temp	ty or City Maintenance Persor	nnel. Use Barr rists to stay of	icade Tape, traf	eured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may	
[ ] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)				
		=		idge is not State maintained )	
			cal law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	_			
	<ul> <li>The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.</li> </ul>				

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance idge on the selected detour route shall be checked				
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>				
CONTACT PERSONNEL:	TELEPHONE NUMBER:				
COUNTY MAYOR'S OFFICE	(615) 384-2476				
HWY. CHIEF ADMINISTRATOR'S OFFICE	(615) 384-2507				
COUNTY SHERIFF'S OFFICE	(615) 384-7971				
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>					
COMMENTS:					
Suggested List of Equipment to conduct the Inspect  Latest Bridge Inspection Report  Scour POA Report with the above Checklist	ion:				
Bridge Design Plans, if available					
Tape measure with weight					
Plumb bob					
Range Pole					
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:				
CALETY HAZADD MEED	AMAY				

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24