## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 76023850001

BRIDGE OWNER: SCOTT COUNTY

ROAD NAME: HUNTSVILLE HILL RD

CROSSING: PAINT ROCK CREEK

LATITUDE:: N 36.45150 DEGREES

LONGITUDE: W 84.47710 DEGREES

COUNTY: SCOTT
ROUTE: 02385
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.21
YEAR BUILT: 1965

		TYPE OF SUPE	RSTRUCTURE =		
MAIN SPAN:	PRESTRESSED CONCRETE - BOX I GIRDERS - MULTIPLE		APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUB	STRUCTURE -		
ABUTMENTS:	: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION				
BENTS: NOT APPLICABLE					
PIERS:	PIER WALL FOR CONCRETE BOX O	ON CONCRETE SP	READ FOOTING F	OUNDATION	
		SCOUR EVA	ALUATION =		
	nknown foundations. Risk of sco cant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.	
		INSPECTION P	ROCEDURES -		
What Initiated the Call-out Inspection?		[ ] Bridge	Watch Alert		
		[ ] TDOT [	District or Loca	al Maintenance Personnel	
		[ ] THP or	Local Law Enf	forcement Personnel	
		[ ] Other:			
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec [ ] - Revie	check for plumb of piers or being the for embankment erosion the for drift build-up on piers or the pier exposure, if possible, ar the latest bridge inspection	ell as vertically n along curb li nts. bents nd compare to	ne, both bridge previous inspe		
If Closure is	recommended:				
Coun temp	ty or City Maintenance Persor	nnel. Use Barri rists to stay off	cade Tape, traf	eured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	-	•	•	
		=	-	idge is not State maintained )	
			cal law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	•			
	<ul> <li>The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.</li> </ul>				

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ill work with State District maintenance or local highway maintenance our route. Any bridge on the selected detour route shall be checked ute.			
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(423) 663-2000			
HWY. CHIEF ADMINISTRATOR'S OFF	FICE (423) 663-3831			
COUNTY SHERIFF'S OFFICE	(423) 663-2245			
1 - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.				
COMMENTS:				
Suggested List of Equipment to con	duct the Inspection:			
Latest Bridge Inspection Report Scour POA Report with the above C	hocklist			
Bridge Design Plans, if available	HECKIIST			
Tape measure with weight				
Plumb bob				
Range Pole				
•	ene Barricade Tape printed with the following message:			
SAFETY	Y HAZARD KEEP AWAY			

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24