HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 770A0050001

BRIDGE OWNER: CITY OF DUNLAP

ROAD NAME: OLD YORK HWY

CROSSING: BIG BRUSH CREEK

LATITUDE:: N 35.40437 DEGREES
LONGITUDE: W 85.38845 DEGREES

COUNTY: SEQUATCHIE
ROUTE: 0A005
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.26

LON	IGITUDE: W 85.38845 DEGREES	5	YEAR BUILT: 1967
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE		NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TMENTS: CONCRETE STUB ABUTMENT ON STEEL PILE FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	N STEEL PILE FOUNDATION	
		SCOUR EVALUATION	
	our critical; bridge foundations de ing scour countermeasures.	etermined to be unstable for cal	lculated scour conditions. Monitor bridge in
		- INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
	·	[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
[] - Span 1. C 2. C [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflectio check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an ew the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous inspe	
f Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if bi	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge		
	Bridge should remain closed until the water recedes and a daylight visual inspection is made		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance by bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(423) 949-2115		
POLICE OFFICE	(423) 949-2115		
PUBLIC WORKS DIRECTOR	(423) 949-2115		
The report shall include the date and time as appropriate, photographs of the bridge	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to conduct the Ins	pection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricad	de Tape printed with the following message:		
SAFETY HAZARD K	EEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24