HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 78024410003
BRIDGE OWNER: SEVIER COUNTY
ROAD NAME: SHILOH CH RD
CROSSING: HAPPY CREEK

LATITUDE:: N 35.87308 DEGREES
LONGITUDE: W 83.69122 DEGREES

COUNTY: SEVIER
ROUTE: 02441
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.50
YEAR BUILT: 1918

LON	NGHODE. W 83.09122 DEGREES	•	TEAN BOILT. 1916
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON ROCK FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION =	
Dridge bee I	unknown foundations. Disk of on		bridge shall be monitored for distress
•	icant flood events. Monitor bridge		•
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		•	al Maintenance Personnel
		[] THP or Local Law Ent	
		[] Other:	
2. C [] - Chec [] - Chec [] - Chec	Check displacement / deflection Check for plumb of piers or being the left of	nts. bents nd compare to previous inspe	
	recommended: at bridge with vehicle pulled a	cross road until bridge is sec	eured and properly closed by District,
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, trat rists to stay off of the bridge	fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
	• •		ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any b prior to signing the detour route.	ridge on the selected detour route shall be checked	
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
<u>c</u>	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
c	COUNTY MAYOR'S OFFICE	(865) 453-6136	
H	WY. CHIEF ADMINISTRATOR'S OFFICE	(865) 453-3452	
c	COUNTY SHERIFF'S OFFICE	(865) 453-4668	
a: se	s appropriate, photographs of the bridge and	he inspection, a brief summary of findings and, distream channel measurements. If significant e copied to Bridge Inspection Headquarters.	
	sted List of Equipment to conduct the Inspec	etion:	
	Bridge Inspection Report POA Report with the above Checklist		
	Design Plans, if available		
_	easure with weight		
Plumb	_		
Range			
_	Foot Roll of yellow Polyethylene Barricade	ape printed with the following message:	
	SAFETY HAZARD KEE		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24