HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 780A0650001
BRIDGE OWNER: SEVIER COUNTY
ROAD NAME: MATTHEW LANE
CROSSING: BOYDS CREEK

LATITUDE:: N 35.89713 DEGREES LONGITUDE: W 83.69310 DEGREES

COUNTY: SEVIER
ROUTE: 0A065
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.36
YEAR BUILT: 1970

2011011022. 11 00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	12/11/20121. 10/0
	TYPE OF SUP	ERSTRUCTURE
MAIN SPAN: STEEL - STRIN	GER/MULTI-BEAM OR GIRDER	APPR. SPAN: NOT APPLICABLE
	TYPE OF SU	BSTRUCTURE
ABUTMENTS: CONCRETE FU	LL HEIGHT ABUTMENT ON CONCRE	TE SPREAD FOOTING FOUNDATION
BENTS: NOT APPLICAE	BLE	
PIERS: NOT APPLICAE	JLE	
	SCOUR F	VALUATION
Bridge has unknown found		determined. The bridge shall be monitored for distress
	nts. Monitor bridge in lieu of inst	
	INSPECTION	PROCEDURES -
What Initiated the Call-ou	ut Inspection? [] Bridg	eWatch Alert
		District or Local Maintenance Personnel
		or Local Law Enforcement Personnel
		:
Things to check on a brid	dge during floods:	
[] - Span movement - I	norizontally as well as vertical	lv
	-	line, both bridge rails and outer edge of bridge deck.
	nb of piers or bents.	
[] - Check for embanki	•	
	d-up on piers or bents	
	re, if possible, and compare to	previous inspection
	ridge inspection report versu	•
[] Novion and larger a		
If Closure is recommende	<u>:d:</u>	
County or City Mai	ntenance Personnel. Use Barı es to warn motorists to stay o	ntil bridge is secured and properly closed by District, ricade Tape, traffic cones and/or traffic flares as iff of the bridge until such time as the bridge may
[] - Contact: (1) Distric	ct Maintenance Supervisor (i	f bridge is State maintained)
' ' '	·	
(3) Tonne	r County Highway Maintenand	ce Official (if bridge is not State maintained)
(3) 1611116	, , ,	-
` ,	, , ,	ce Official (if bridge is not State maintained)

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ith State District maintenance or local highway maintenance Any bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(865) 453-6136		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(865) 453-3452		
COUNTY SHERIFF'S OFFICE	(865) 453-4668		
The report shall include the date and time as appropriate, photographs of the bridge	e inspection to BridgeWatch scour monitoring system. ne of the inspection, a brief summary of findings and, ge and stream channel measurements. If significant also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the I	nspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	cade Tape printed with the following message:		
SAFETY HAZARD	KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24