HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 79051360001 BRIDGE OWNER: CITY OF MEMPHIS

ROAD NAME: REESE RD CROSSING: BRANCH

LATITUDE:: N 35.19503 DEGREES

COUNTY: SHELBY ROUTE: 05136 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 2.11

LON	NGITUDE: W 89.82656 DEGREES	S YEAR BUILT: 1985
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	CONCRETE PILE FOUNDATION
BENTS:	CONCRETE COLUMN TWO POST E	BENT ON CONCRETE PILE FOUNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has u	unknown foundations. Risk of sc	our cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. 0 2. 0 [] - Chec [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	on along curb line, both bridge rails and outer edge of bridge deck. onts.
f Closure is	recommended:	
Cour temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(901) 576-6007		
CITY ENGINEER'S OFFICE	(901) 576-6902		
PUBLIC WORKS DIRECTOR	(901) 576-7109		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. COMMENTS:			
Suggested List of Equipment to conduct the Inspec	etion:		
Latest Bridge Inspection Report Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade 1	ape printed with the following message:		
SAFETY HAZARD KEE			
A Barricade Tape Dispenser with serrated cutter			

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

A roll of Duct Tape