HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 790A7280001

BRIDGE OWNER: CITY OF COLLIERVILLE

ROAD NAME: FRANK RD
CROSSING: BRANCH

LATITUDE:: N 35.06950 DEGREES
LONGITUDE: W 89.71869 DEGREES

COUNTY: SHELBY
ROUTE: 05571
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.67
YEAR BUILT: 1962

201	1011052: 11 00111000 DEGREES	12/11/201211 1002
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	CONCRETE PILE FOUNDATION
BENTS:	CONCRETE COLUMN FOUR OR MC	PRE POST BENT ON PILE FOUNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Dridge is see	our critical: bridge foundations de	
		etermined to be unstable for calculated scour conditions. Rip-rap protection of me minor repairs to the protection system are needed.
		INSPECTION PROCEDURES
What Initiat	ted the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
	-	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
		nd compare to previous inspection
		report versus current field conditions
• •		
If Closure is	recommended:	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(901) 457-2200		
CITY ENGINEER'S OFFICE	(901) 457-2310		
POLICE OFFICE	(901) 457-2513		
- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	ction:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade 1			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24