## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 79M28770005 BRIDGE OWNER: CITY OF MEMPHIS ROAD NAME: WHITTEN RD CROSSING: FLETCHER CREEK

COUNTY: SHELBY ROUTE: **05131** SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 35.18783 DEGREE IGITUDE: W 89.83589 DEGREE	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - STR OR GIRDER	NGER/MULTI-BEAM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
	CONCRETE STUB ABUTMENT ON	CONCRETE PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		cour cannot be determined. The bridge shall be monitored for distress t scour countermeasure protective system has been installed.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers of k pier exposure, if possible, a	vell as vertically on along curb line, both bridge rails and outer edge of bridge deck. ents.
lf Closure is	recommended:	
Coun temp	ity or City Maintenance Perso	across road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
[ ] - Conta		Supervisor ( if bridge is State maintained )
	` ' ' ' '	ay Maintenance Official ( if bridge is not State maintained )
		Patrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridg	_
	lge should remain closed until the water recedes and a daylight visual inspection is made	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PE	ERSONNEL:	TELEPHONE NUMBER:	
CITY MAYOR	'S OFFICE	(901) 576-6007	
CITY ENGINE	EER'S OFFICE	(901) 576-6902	
PUBLIC WOF	RKS DIRECTOR	(901) 576-7109	
The report as appropri	] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
Suggested List o	of Equipment to conduct the Inspec	etion:	
Latest Bridge Ins	spection Report		
•	ort with the above Checklist		
Bridge Design Pl			
Tape measure wi	ith weight		
Plumb bob			
Range Pole	of wellow Debugths love Demise de 3	Fanna mainta dunith tha fallannin managara	
A 1000 FOOt ROII	SAFETY HAZARD KEE	Tape printed with the following message:	
	SAFEIT MAZAKU KEE	T AVVA I	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24