## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 79\$80740003

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: COLLIERVILLE-ARLINGTON RD

CROSSING: OVERFLOW

LATITUDE:: N 35.07853 DEGREES
LONGITUDE: W 89.65181 DEGREES

COUNTY: SHELBY
ROUTE: 05757
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.34

LON	NGITUDE: W 89.65181 DEGREES	YEAR BUILT: 1959	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	TYPE OF SUPERSTRUCTURE  APPR. SPAN: NOT APPLICABLE	
WAIN OF AIN.	CONCRETE - CHANNEL BEAM		
		TYPE OF SUBSTRUCTURE	
ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION			
BENTS:	CONCRETE PILE BENT ON PILE FO	UNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	·	TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
[ ] - Span	movement - horizontally as w	ell as vertically	
	•	n along curb line, both bridge rails and outer edge of bridge deck.	
2. 0	Check for plumb of piers or bei	nts.	
[ ] - Chec	k for embankment erosion		
[ ] - Chec	k for drift build-up on piers or	bents	
[ ] - Chec	k pier exposure, if possible, ar	nd compare to previous inspection	
[ ] - Review the latest bridge inspection report versus current field conditions			
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(901) 484-2610		
TENNESSEE HIGHWAY PATROL	(901) 543-6256		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct the Inspect	ion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

**SAFETY HAZARD KEEP AWAY** 

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**