HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 890A3200001

BRIDGE OWNER: WARREN COUNTY

ROAD NAME: SAM MCGEE RD

CROSSING: POWDER MILL BRANCH

LATITUDE:: N 35.65892 DEGREES
LONGITUDE: W 85.67403 DEGREES

COUNTY: WARREN
ROUTE: 0A320
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.41
YEAR BUILT: 1960

20.	1011022: 11 00:01400 DIGHT			12/4K BOILT: 1000
		TYPE OF SUPER	RSTRUCTURE =	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBS	STRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN	I FOUNDATION	
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVA		
	unknown foundations. Risk of sco licant flood events. Monitor bridge			bridge shall be monitored for distress stermeasures.
		INSPECTION P	ROCEDURES -	
What Initiat	ed the Call-out Inspection?	[] Bridge\	Natch Alert	
	·			al Maintenance Personnel
				forcement Personnel
1. C 2. C	Check for plumb of piers or be	n along curb lii		e rails and outer edge of bridge deck.
	k for embankment erosion	l		
	k for drift build-up on piers or			andia n
	k pier exposure, if possible, ar	-	-	
[] - Revie	ew the latest bridge inspection	report versus	current field c	onditions
lf Closure is	recommended:			
[] - Stay a Coun temp	at bridge with vehicle pulled a nty or City Maintenance Persor	nnel. Use Barrio ists to stay off	cade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if I	oridge is State	maintained)
	(2) City or County Highwa	y Maintenance	Official (if bi	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or loc	al law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	Bridge should remain closed u TDOT bridge inspection team.		ecedes and a	daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any be prior to signing the detour route.	ridge on the selected detour route shall be checked	
[]-] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
	COUNTY MAYOR'S OFFICE	(931) 473-2505	
	HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 473-2007	
	COUNTY SHERIFF'S OFFICE	(931) 473-7863	
Lates Scour Bridge	ested List of Equipment to conduct the Inspect t Bridge Inspection Report POA Report with the above Checklist Design Plans, if available	etion:	
l ape	measure with weight		
	e Pole		
_	0 Foot Roll of yellow Polyethylene Barricade	ape printed with the following message:	
	SAFETY HAZARD KEE		

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)