HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 890A5190005
BRIDGE OWNER: WARREN COUNTY
ROAD NAME: IVY BLUFF RD
CROSSING: BARREN FORK RIVER
LATITUDE:: N 35.67785 DEGREES
LONGITUDE: W 85.95185 DEGREES

COUNTY: WARREN
ROUTE: 01112
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 5.64
YEAR BUILT: 1978

		TYPE OF SUPE	RSTRUCTURE -		
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE	NUOUS -	APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUB	STRUCTURE -		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON STEEL PILE FOUNDATION				
BENTS:	ENTS: NOT APPLICABLE				
PIERS:	CONCRETE HAMMERHEAD PIER ON STEEL PILE FOUNDATION				
		SCOUR EV	ALUATION =		
	our critical; bridge foundations de ing scour countermeasures.			culated scour conditions. Monitor bridge in	
		INSPECTION P	ROCEDURES =		
What Initiated the Call-out Inspection?		[] Bridge	Watch Alert		
				al Maintenance Personnel	
		[] THP or	Local Law Enf	forcement Personnel	
1. C 2. C [] - Chec [] - Chec	movement - horizontally as we heck displacement / deflection check for plumb of piers or being the head of the hea	n along curb li nts. bents nd compare to	ne, both bridge		
<u>lf Closure is</u>	recommended:				
Coun temp	ty or City Maintenance Persor	nnel. Use Barri rists to stay of	cade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
[] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)				
	(2) City or County Highwa	y Maintenance	Official (if br	idge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or lo	cal law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer			
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any bri	idge on the selected detour route shall be checked			
	idge can be re-opened only after a TDOT bridge inspection team checks the substructure and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(931) 473-2505			
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 473-2007			
COUNTY SHERIFF'S OFFICE	(931) 473-7863			
The report shall include the date and time of th as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	stream channel measurements. If significant copied to Bridge Inspection Headquarters.			
Suggested List of Equipment to conduct the Inspect	ion:			
Latest Bridge Inspection Report				
Scour POA Report with the above Checklist				
Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:			
SAFETY HAZARD KEEP	AWAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24