HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 92008590001
BRIDGE OWNER: WEAKLEY COUNTY

ROAD NAME: OLD SR22

CROSSING: SPRING CREEK BRANCH
LATITUDE:: N 36.16107 DEGREES
LONGITUDE: W 88.54781 DEGREES

COUNTY: WEAKLEY
ROUTE: 00859
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.78
YEAR BUILT: 1950

LON	NGHODE. W 66.54761 DEGREES	I LAN BOILT. 1930
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON CONCRETE SPREAD FOOTING FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
•	our critical; bridge foundations de sures are installed but they are r	etermined to be unstable for calculated scour conditions. No scour needed.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
1. 0	Check displacement / deflectio	n along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	nts.
[] - Chec	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
[] - Chec	k pier exposure, if possible, a	nd compare to previous inspection
[] - Revie	ew the latest bridge inspection	report versus current field conditions
lf Clasura is	rasammandadı	
	recommended:	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	with State District maintenance or local highway maintenance e. Any bridge on the selected detour route shall be checked		
[] - The bridge can be re-opened only afte units and they are determined to be st	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 364-5413		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 364-2284		
COUNTY SHERIFF'S OFFICE	(731) 364-5454		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Latest Bridge Inspection Report Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight Plumb bob			
Range Pole			
•	ricade Tape printed with the following message:		
SAFETY HAZAD			

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape