HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 920A4690003 BRIDGE OWNER: WEAKLEY COUNTY ROAD NAME: ETHRIDGE LEVEE RD

CROSSING: BRANCH

LATITUDE:: N 36.20033 DEGREES

COUNTY: WEAKLEY ROUTE: 0A469 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.33

LON	IGITUDE: W 88.86900 DEGREES	YEAR BUILT: 1970
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE CONTIN STRINGER/MULTI-BEAM OR GIRDE	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION
BENTS:	CONCRETE PILE BENT ON PILE FO	UNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
	our critical; bridge foundations de ing scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or l k pier exposure, if possible, an	along curb line, both bridge rails and outer edge of bridge deck.
If Closure is	recommended:	
Coun temp	ity or City Maintenance Person	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as stay off of the bridge until such time as the bridge may
-	• •	upervisor (if bridge is State maintained)
	(2) City or County Highway	Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made FDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 364-5413		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 364-2284		
COUNTY SHERIFF'S OFFICE	(731) 364-5454		
The report shall include the date a as appropriate, photographs of the	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to conduct	t the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Check	dist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene	Barricade Tape printed with the following message:		
SAFETY HA	ZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24