HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 92SR0220023

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: SR22

CROSSING: CHESTNUT BRANCH
LATITUDE:: N 36.29833 DEGREES
LONGITUDE: W 88.75167 DEGREES

COUNTY: WEAKLEY
ROUTE: SR022
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 15.75

LON	MOTIODE. W 66.75167 DEGREE	TEAN BOILT. 1901	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	CONCRETE PILE FOUNDATION	
BENTS:	CONCRETE PILE BENT ON PILE FO	TE PILE BENT ON PILE FOUNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Bridge is so	our critical: bridge foundations de	etermined to be unstable for calculated scour conditions. Monitor bridge in	
-	ling scour countermeasures.	stermined to be unstable for calculated scour conditions. Monitor bridge in	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
Things to c	heck on a bridge during flood	<u>s:</u>	
[] - Span	movement - horizontally as w	rell as vertically	
	•	n along curb line, both bridge rails and outer edge of bridge deck.	
2. 0	Check for plumb of piers or be	nts.	
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or	bents	
[] - Chec	k pier exposure, if possible, a	nd compare to previous inspection	
[] - Review the latest bridge inspection report versus current field conditions			
<u>If Closure is</u>	recommended:		
Coun temp	ity or City Maintenance Persoi	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[] - Contact: (1) District Maintenan		Supervisor (if bridge is State maintained)	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	e Engineer	
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any br prior to signing the detour route.	idge on the selected detour route shall be checked	
- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
REGION BRIDGE ENGINEER	(731) 234-9561	
DISTRICT MAINTENANCE SUPERVISOR	(731) 571-8883	
TENNESSEE HIGHWAY PATROL	(731) 423-6635	
as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	e copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspect	ion:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:	
SAFETY HAZARD KEEP	AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24