HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 940A0440001

BRIDGE OWNER: WILLIAMSON COUNTY

ROAD NAME: **BLAZER RD**CROSSING: **BRANCH**

LATITUDE:: N 35.92177 DEGREES
LONGITUDE: W 86.96135 DEGREES

COUNTY: WILLIAMSON
ROUTE: 0A044
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.58

LOr	NGH UDE: W 86.96135 DEGREES	YEAR BUILT: 1965	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	UTMENTS: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	-	[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
[] - Span 1. (2. ([] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.	
<u>If Closure is</u>	recommended:		
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



0	 The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route. 		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
<u>C</u>	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
С	COUNTY MAYOR'S OFFICE	(615) 790-5700	
н	WY. CHIEF ADMINISTRATOR'S OFFICE	(615) 790-5598	
С	COUNTY SHERIFF'S OFFICE	(615) 790-5560	
Ti as	ummarize and submit findings from the inspec he report shall include the date and time of the s appropriate, photographs of the bridge and s couring has occurred, the report shall also be o	inspection, a brief summary of findings and, tream channel measurements. If significant	
COMME	NTS:		
Sugges	sted List of Equipment to conduct the Inspection	<u>on:</u>	
Latest E	Bridge Inspection Report		
Scour F	POA Report with the above Checklist		
_	Design Plans, if available		
•	easure with weight		
Plumb I			
Range I		a uninted suith the following management	
A 1000	Foot Roll of yellow Polyethylene Barricade Tap SAFETY HAZARD KEEP A		
	SAFETT HAZARU KEEP A	AVVA I	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)