

CARROLL COUNTY

09-SR436-0068


Federal ID: 09S82330001

Road Name:

Crossing: REEDY CREEK

OVR/UND PASS:

Road Name 2:



Bridge Loc. No: 09 - SR436 - 00.68 Date: 09-12-19



BRIDGE NO.



REPLACED BENT #1 CAP AND BOLTED STRAPS TO CAP AND PILING

Bridge Loc. No: 09 - SR436 - 00.68 Date: 09-12-19



REPLACED BENT #1 CAP AND BOLTED STRAPS TO CAP AND PILING



REPLACED BENT #1 CAP AND BOLTED STRAPS TO CAP AND PILING

Bridge Maintenance Recommendations



Page No. _____

Page 1 of 1

Bridge Location No.: **09 - SR436 - 0068**

Co. Route Log Mile

Crossing: REEDY CREEK

Road Name:

Road Name #2:

Bridge Rating: FAIR

Inspection Cycle: 25 County: CARROLL

Inspection Date: 8/15/2019 City:

G.P.S.: Comments:

N36 0.8600

W88 32.4583

Bridge Number: **09S82330001**

Over/Underpass

No:

Region: 04

District: 47 Spec.Cas 0

Maint.Resp 02 Co.Seq: 01

Pipes:

	@	' x '
Barrels	Length	Width

RECOMMENDATIONS:

Maintenance Completed: by/date

SUGGESTED ROUTINE MAINTENANCE:

238	BRIDGERAILS ARE SUBSTANDARD
229	APPROACH GUARDRAILS ARE NON-EXISTENT
135	REPAIR _TIMBER_ CAP AT _BENT_ NO. _1B (REPAIRED BY BRIDGE REPAIR 09-05-19)
204	CUT VEGETATION

COMMENTS:

BRIDGE MAINTENANCE RECOMMENDATIONS

NTY: CARROLL

TION: 9-SR436-00.68-

CO. SEQ.: 1

SPEC. CASE: 0



Tennessee Department
of Transportation

CROSSING: REEDY CREEK

FED. BRIDGE NO.: 09S82330001

MAINT. DIST.: 9

REPAIR LIST NO.: N

DATE ADDED: 03/12/2012

REVISED: 08/15/2019

FACILITY CARRIED:	FAS 436	NUMBER OF MAIN SPANS:	1
HIGHWAY SYSTEM:	05-STP RURAL, STATE	NUMBER OF APPROACH SPANS:	3
BRIDGE WIDTH (CURB TO CURB):	20 FT 4 IN	BRIDGE LENGTH (FT):	90
BRIDGE WIDTH (OUT TO OUT):	21 FT 7 IN	MAXIMUM SPAN LENGTH (FT):	33
APPROACH ROADWAY (W/SHOULDERS):	27 FT 10 IN	SKEW ANGLE (DEGREES):	90
MAINTAINED BY:	STATE HIGHWAY AGENCY		
MAIN SPAN MATERIAL:	PRESTRESSED CONCRETE		
MAIN SPAN DESIGN TYPE:	BOX BEAM OR GIRDERS - MULTIPLE		
APPROACH SPAN MATERIAL:	CONCRETE		
APPROACH SPAN DESIGN TYPE:	SLAB		
INSPECTION DATE:	08/15/2019	GENERAL CONDITION:	FAIR
EVALUATION DATE:	10/09/2017	STRUCTURALLY DEFICIENT:	NO
PPRM PIN NUMBER:	124139.00	SUFFICIENCY RATING:	60.2
H TRUCK RATING @ INV.:	15 TONS		

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS

REPAIR CAPBEAM AT BENT NO.1B $\longleftrightarrow$ 9-5-2019

CUT AND REMOVE VEGETATION FROM CHANNEL

APPROACH GUARDRAILS ARE NON-EXISTENT

BRIDGERAILS ARE SUBSTANDARD

GENERAL COMMENTS:

BRIDGE IS ON THE IMPROVE ACT. EARLIEST LETTING DATE FOR REPLACEMENT IS CY 2021.

Replace Capbeam Bent No 1.B right + left side with new cap and Bolt straps to cap and piers.