HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 42FA1230001

BRIDGE OWNER: STATE OF TENNESSEE
ROAD NAME: HURRICANE CREEK RD
CROSSING: HURRICANE CREEK
LATITUDE:: N 36.33333 DEGREES

COUNTY: HOUSTON
ROUTE: SR232
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.78

	TITUDE:: N 36.33333 DEGREES GITUDE: W 87.91500 DEGREES	LOG MILE: 1.78 YEAR BUILT: 1961	
LON		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
WAIN SPAN.	CONCRETE - TEE BEAIN	AFFR. SFAN. NOI AFFLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	TEEL PILE FOUNDATION	
BENTS:		ENT ON CONCRETE PILE FOUNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	our critical; bridge foundations de ing scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	•	[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
1. C 2. C [] - Checl [] - Checl	check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. sts.	
If Closure is	recommended:		
Countempo	 Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. 		
[] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)			
	(2) City or County Highwa	Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(615) 476-8860		
DISTRICT MAINTENANCE SUPERVISOR	(931) 205-6399		
TENNESSEE HIGHWAY PATROL	(615) 741-3181		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. COMMENTS: 			
Suggested List of Equipment to conduct the Inspec	ction:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:		
SAFETY HAZARD KEE	P AWAY		
A Barricade Tape Dispenser with serrated cutter			

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

A roll of Duct Tape