HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 43018060001

BRIDGE OWNER: HUMPHREYS COUNTY ROAD NAME: E BIG RICHLAND CIR

CROSSING: DEER CREEK

LATITUDE" N 36 16258

COUNTY: HUMPHREYS

ROUTE: 01806 SPECIAL CASE: 0

COUNTY SEQUENCE: 1

LOG MILE: 0.08

	IGITUDE: W 87.75327 DEGREES	YEAR BUILT: 1970	
LOIN			
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX B GIRDERS - SINGLE OR SPREAD	EAM OR APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMEN	IT ON CONCRETE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	STEEL PILE FOUNDATION	
		SCOUR EVALUATION	
		hat extensive scour has occurred at bridge foundations. Immediate action . Monitor bridge in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or ben k for embankment erosion k for drift build-up on piers or l k pier exposure, if possible, an	along curb line, both bridge rails and outer edge of bridge deck. ts.	
If Closure is	recommended:		
Coun temp	ity or City Maintenance Person	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)	
	(2) City or County Highway	Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	he Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



0		e District maintenance or local highway maintenance dge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
<u>C</u>	ONTACT PERSONNEL:	TELEPHONE NUMBER:	
C	OUNTY MAYOR'S OFFICE	(931) 296-7795	
H	WY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121	
C	OUNTY SHERIFF'S OFFICE	(931) 296-2301	
Th as	[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMEN	ITS:		
<u>Sugges</u>	ted List of Equipment to conduct the Inspecti	on:	
Latest E	Bridge Inspection Report		
Scour P	OA Report with the above Checklist		
Bridge I	Design Plans, if available		
Tape me	easure with weight		
Plumb b	oob		
Range F	Pole		
A 1000 I	Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:	
	SAFETY HAZARD KEEP	AWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)