## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 930A4690001
BRIDGE OWNER: WHITE COUNTY
ROAD NAME: FARLEY RD
CROSSING: POST OAK CREEK
LATITUDE:: N 36.06578 DEGREES

COUNTY: WHITE
ROUTE: 0A469
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.45

	.ATITUDE:: N 36.06578 DEGREES DNGITUDE: W 85.50085 DEGREES		
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:		APPR. SPAN: NOT APPLICABLE	
	CONONETE CEAS		
		TYPE OF SUBSTRUCTURE ————————————————————————————————————	
	S: CONCRETE BOX TYPE ON CONCRI	ETE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	•	[ ] TDOT District or Local Maintenance Personnel	
		THP or Local Law Enforcement Personnel	
		[ ] Other:	
1. 2. [ ] - Che [ ] - Che	Check for plumb of piers or be cck for embankment erosion cck for drift build-up on piers or cck pier exposure, if possible, an	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
<u>If Closure i</u>	is recommended:		
[ ] - Stay Cou tem	y at bridge with vehicle pulled a unty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[ ] - Contact: (1) District Maintenance Supervisor ( if bridge is State maintained )		Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



[]-		ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked	
[]-	he bridge can be re-opened only after a TDOT bridge inspection team checks the substructure nits and they are determined to be structurally stable.		
	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
	COUNTY MAYOR'S OFFICE	(931) 836-3203	
	HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 738-2110	
	COUNTY SHERIFF'S OFFICE	(931) 836-3621	
	The report shall include the date and time of as appropriate, photographs of the bridge an	pection to BridgeWatch scour monitoring system. the inspection, a brief summary of findings and, d stream channel measurements. If significant be copied to Bridge Inspection Headquarters.	
СОММ	ENTS:		
Sugge	ested List of Equipment to conduct the Inspe	ction:	
Lates	t Bridge Inspection Report		
Scour	POA Report with the above Checklist		
_	e Design Plans, if available		
•	measure with weight		
Plumi			
_	e Pole		
A 100	0 Foot Roll of yellow Polyethylene Barricade		
	SAFETY HAZARD KEE	PAWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**