## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 12S80580007 BRIDGE OWNER: CHESTER COUNTY ROAD NAME: GARLAND RD CROSSING: OVERFLOW

> LATITUDE" N 35 49025 DEGREES

COUNTY: CHESTER ROUTE: 00926 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1 78

	IGITUDE: W 88.64700 DEGREE	
LON	19110DE. W 68.04700 DEGREE	TEAR BUILL 2002
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - STR OR GIRDER	NGER/MULTI-BEAM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	STEEL PILE FOUNDATION
BENTS:	STEEL PILE BENT ON STEEL PILE	FOUNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
event. Deter		have been installed to reduce the risk of bridge failure during a flood riprap should be reported to TDOT for assessment. Rip-rap protection ha
		INSPECTION PROCEDURES ————————————————————————————————————
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers o k pier exposure, if possible, a	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
<u>lf Closure is</u>	recommended:	
Coun temp	ty or City Maintenance Perso	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance	Supervisor ( if bridge is State maintained )
	(2) City or County Highw	y Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway F	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made FDOT bridge inspection team.	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	n State District maintenance or local highway maintenance ny bridge on the selected detour route shall be checked
[ ] - The bridge can be re-opened only after a units and they are determined to be structured.	TDOT bridge inspection team checks the substructure turally stable.
CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(731) 989-5672
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 989-7311
COUNTY SHERIFF'S OFFICE	(731) 989-2787
	and stream channel measurements. If significant so be copied to Bridge Inspection Headquarters.
Suggested List of Equipment to conduct the Ins	spection:
Latest Bridge Inspection Report	
Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricae SAFETY HAZARD K	
A Barricade Tape Dispenser with serrated cutter	
A roll of Duct Tape	
•	
• •	t of electronic warning flashers
Traffic Cones - Minimum of four (4)  Traffic Safety Flares - Minimum of four (4) or set	t of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**