HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: GIBSON ROUTE: 00860

BRIDGE ID NUMBER: 27008600019 BRIDGE OWNER: GIBSON COUNTY ROAD NAME: CADES - ATWOOD RD

LATITUDE:: N 35.97528 DEGREES

SPECIAL CASE: 0 CROSSING: MAYS CREEK COUNTY SEQUENCE: 1 LOG MILE: 6.50 LONGITUDE: W 99 77753 DEGDEES VEAR BILLT: 1006

LOI	NOTIODE. W 66.77793 DEGREE	S TEAN BOILT. 1990
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOL	
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		OCCUP FIVE LIATION
5		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress ge in lieu of installing scour countermeasures.
-		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
[] - Span	movement - horizontally as w	vell as vertically
	•	on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
	k for drift build-up on piers or	bents
	• •	nd compare to previous inspection
		n report versus current field conditions
If Closure is	recommended:	
Cour temp	nty or City Maintenance Person	ncross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
• • •		Supervisor (if bridge is State maintained)
_	• •	ay Maintenance Official (if bridge is not State maintained)
	` ' '	Patrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	
	Bridge should remain closed u TDOT bridge inspection team.	until the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	e District maintenance or local highway maintenance dge on the selected detour route shall be checked	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 855-7611	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684	
COUNTY SHERIFF'S OFFICE	(731) 855-1121	
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:		
Suggested List of Equipment to conduct the Inspection Latest Bridge Inspection Report	<u>on:</u>	
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade Ta		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19