HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 270A3580001
BRIDGE OWNER: GIBSON COUNTY
ROAD NAME: BOBBY BURGESS RD

CROSSING: BRANCH

COUNTY: GIBSON
ROUTE: 0A358
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.01
YEAR BUILT: 1971

	TITUDE:: N 36.00297 DEGREES		
LON			
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU	TYPE OF SUPERSTRUCTURE ILTI-BEAM OR APPR. SPAN: NOT APPLICABLE	
WAIN OF AN.	GIRDER	ILIPBEAN ON ALTA. NOT AFFEIGABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOL	INDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Bridge has u	ınknown foundations. Risk of sc	our cannot be determined. The bridge shall be monitored for distress	
		e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	·	[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
Things to c	heck on a bridge during flood	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
	•	n along curb line, both bridge rails and outer edge of bridge deck.	
	Check for plumb of piers or be	nts.	
	k for embankment erosion		
	k for drift build-up on piers or		
		nd compare to previous inspection	
[] - Review the latest bridge inspection report versus current field conditions			
If Closure is	recommended:		
[] - Stay a	at bridge with vehicle pulled a	cross road until bridge is secured and properly closed by District,	
	-	nnel. Use Barricade Tape, traffic cones and/or traffic flares as	
	orary measures to warn moto operly closed and barricaded.	rists to stay off of the bridge until such time as the bridge may	
•	• •	Supervisor (if bridge is State maintained)	
[] 00	• •	y Maintenance Official (if bridge is not State maintained)	
		atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge		
[] - The E	` '	ntil the water recedes and a daylight visual inspection is made	
by a	TDOT bridge inspection team.	·	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any bri prior to signing the detour route. 	e District maintenance or local highway maintenance dge on the selected detour route shall be checked	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 855-7611	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684	
COUNTY SHERIFF'S OFFICE	(731) 855-1121	
The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	stream channel measurements. If significant copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspecti	on:	
	<u>v</u>	
Latest Bridge Inspection Report Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:	
SAFETY HAZARD KEEP	AWAY	
A Barricade Tape Dispenser with serrated cutter		

PUBLICATION DATE

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

17-Apr-19