HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 270B0100001
BRIDGE OWNER: GIBSON COUNTY

ROAD NAME: OLD RUTHERFORD-KENTON RD

CROSSING: EDMONDSON CREEK

LATITUDE:: N 36.15967 DEGREES

LONGITUDE: W 89.01175 DEGREES

COUNTY: GIBSON
ROUTE: 0B010
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.88

LON	NGITUDE: W 89.01175 DEGREES	;	YEAR BUILT: 2008
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	WOOD OR TIMBER - STRINGER/MULTI-BEAM OR GIRDER
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION =	
Bridge been	unknown foundations. Pick of sor		bridge shall be monitored for distress
	ficant flood events. Monitor bridge		
0 0	· ·	-	
What Initiat	and the Call and Imagestics 2	INSPECTION PROCEDURES =	
wnat initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	al Maintananaa Daraannal
		[] THP or Local Law Ent	al Maintenance Personnel
			rorcement Personner
		[] Other.	
Things to c	heck on a bridge during floods	s:	
_	_		
	movement - horizontally as w	•	e rails and outer edge of bridge deck.
	Check displacement / denection		e rails and outer edge of bridge deck.
	k for embankment erosion		
	k for drift build-up on piers or	hants	
	k pier exposure, if possible, a		ection
	ew the latest bridge inspection		
[] - KCAK	w the latest bridge inspection	report versus current neid e	Onditions
If Closure is	recommended:		
[] - Stav	at bridge with vehicle pulled a	cross road until bridge is sec	cured and properly closed by District,
			ffic cones and/or traffic flares as
-	-	-	until such time as the bridge may
-	roperly closed and barricaded.		
[] - Cont	act: (1) District Maintenance S	. , ,	,
		·	ridge is not State maintained)
			ement Officers as appropriate
	(4) TDOT Regional Bridge	=	
	Bridge should remain closed u TDOT bridge inspection team.		daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PER	RSONNEL:	TELEPHONE NUMBER:		
COUNTY MAY	OR'S OFFICE	(731) 855-7611		
HWY. CHIEF A	ADMINISTRATOR'S OFFICE	(731) 855-7684		
COUNTY SHE	RIFF'S OFFICE	(731) 855-1121		
The report s as appropria	shall include the date and time of the ate, photographs of the bridge and s	tion to BridgeWatch scour monitoring system. inspection, a brief summary of findings and, tream channel measurements. If significant copied to Bridge Inspection Headquarters.		
COMMENTS:				
Latest Bridge Insp	Equipment to conduct the Inspection Report twith the above Checklist	<u>n:</u>		
Bridge Design Pla				
Tape measure wit	·			
Plumb bob				
Range Pole				
A 1000 Foot Roll o	of yellow Polyethylene Barricade Tap	e printed with the following message:		
	CAEETV HAZADD KEED A	MAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19