HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 290A3650001
BRIDGE OWNER: GRAINGER COUNTY

ROAD NAME: **BLUFF RD**

CROSSING: RICHLAND CREEK

LATITUDE:: N 36.25210 DEGREES LONGITUDE: W 83.58325 DEGREES

COUNTY: GRAINGER
ROUTE: 0A365
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.09

YEAR BUILT: 1915 TYPE OF SUPERSTRUCTURE MAIN SPAN: STEEL - STRINGER/MULTI-BEAM OR GIRDER APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE FULL HEIGHT ABUTMENT ON SOIL FOUNDATION BENTS: **NOT APPLICABLE** PIERS: **NOT APPLICABLE SCOUR EVALUATION** Bridge has unknown foundations. Risk of scour cannot be determined. The bridge shall be monitored for distress during significant flood events. Monitor bridge in lieu of installing scour countermeasures. **INSPECTION PROCEDURES** [] BridgeWatch Alert What Initiated the Call-out Inspection? [] TDOT District or Local Maintenance Personnel [] THP or Local Law Enforcement Personnel [] Other: _ Things to check on a bridge during floods: [] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [] - Check for embankment erosion [] - Check for drift build-up on piers or bents [] - Check pier exposure, if possible, and compare to previous inspection [] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. [] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained) (2) City or County Highway Maintenance Official (if bridge is not State maintained) (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate

PUBLICATION DATE

(4) TDOT Regional Bridge Engineer

by a TDOT bridge inspection team.

[] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officia] - The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTA	ACT PERSONNEL:	TELEPHONE NUMBER:	
COUN	TY MAYOR'S OFFICE	(865) 828-3613	
HWY.	CHIEF ADMINISTRATOR'S OFFICE	(865) 828-4029	
COUN	TY SHERIFF'S OFFICE	(865) 828-5861	
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested	List of Equipment to conduct the Inspect	tion:	
Latest Bridg	ge Inspection Report		
Scour POA	Report with the above Checklist		
•	gn Plans, if available		
•	ure with weight		
Plumb bob			
Range Pole			
A 1000 Foot	Roll of yellow Polyethylene Barricade Ta		
	SAFETY HAZARD KEEP	AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19