HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 38S81310009
BRIDGE OWNER: HAYWOOD COUNTY
ROAD NAME: POPLAR CORNER RD
CROSSING: MUDDY CREEK

LATITUDE:: N 35.66033 DEGREES
LONGITUDE: W 89.11617 DEGREES

COUNTY: HAYWOOD
ROUTE: 00846
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 8.42
YEAR BUILT: 1957

		TYPE OF SUPERSTRUCTURE =		
MAIN SPAN:	CONCRETE CONTINUOUS - TEE BEA		NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE =		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON CO	ONCRETE PILE FOUNDATION		
BENTS:	ENTS: CONCRETE COLUMN FOUR OR MORE POST BENT ON CONCRETE PILE FOUNDATION			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION -		
	our critical; bridge foundations det sures are installed but they are ne		culated scour conditions. No scour	
		INSPECTION PROCEDURES -		
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert		
	·		Il Maintenance Personnel	
		[] THP or Local Law Enf	orcement Personnel	
		[] Other:		
1. C 2. C [] - Chec [] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or benk for embankment erosion k for drift build-up on piers or be k pier exposure, if possible, and ew the latest bridge inspection in	along curb line, both bridge ts. ents d compare to previous inspe		
<u>If Closure is</u>	recommended:			
 Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. 				
[] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)				
	(2) City or County Highway	Maintenance Official (if br	idge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked		
	ge can be re-opened only after a TDOT bridge inspection team checks the substructure d they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 772-1432		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 772-9423		
COUNTY SHERIFF'S OFFICE	(731) 772-6158		
The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. COMMENTS:			
Suggested List of Equipment to conduct the Insp	pection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricad			
SAFETY HAZARD KE	EEP AWAY		
A Barricade Tape Dispenser with serrated cutter			

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

A roll of Duct Tape