## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 390A0730001

BRIDGE OWNER: HENDERSON COUNTY ROAD NAME: LONGSOUGHT RD

CROSSING: BRANCH

COUNTY: HENDERSON ROUTE: 0A073 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

LATITUDE:: N 35.67369 DEGREES LONGITUDE: W 88.43656 DEGREES	LOG MILE: 0.80 YEAR BUILT: 1965	
	TYPE OF SUPERSTRUCTURE	
MAIN SPAN: WOOD OR TIMBER - STRINGER/MUI GIRDER	LTI-BEAM OR APPR. SPAN: NOT APPLICABLE	
	TYPE OF SUBSTRUCTURE	
ABUTMENTS: TIMBER CAP ON TIMBER PILE FOUL	NDATION	
BENTS: TIMBER PILE BENT ON PILE FOUND	PATION	
PIERS: NOT APPLICABLE		
	SCOUR EVALUATION	
Bridge is scour critical; bridge foundations de lieu of installing scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in	
	INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?	[ ] BridgeWatch Alert	
	[ ] TDOT District or Local Maintenance Personnel	
	[ ] THP or Local Law Enforcement Personnel	
	[ ] Other:	
Things to shook on a bridge during floods		
Things to check on a bridge during floods:		
[ ] - Span movement - horizontally as well as vertically		
-	a along curb line, both bridge rails and outer edge of bridge deck.	
2. Check for plumb of piers or bents.		
[ ] - Check for embankment erosion		
<ul><li>[ ] - Check for drift build-up on piers or bents</li><li>[ ] - Check pier exposure, if possible, and compare to previous inspection</li></ul>		
[ ] - Review the latest bridge inspection report versus current field conditions		
[ ] - Neview the latest bridge inspection	report versus current neia contantoris	
If Clasura is recommended.		
If Closure is recommended:		
County or City Maintenance Person	eross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[ ] - Contact: (1) District Maintenance Se	upervisor ( if bridge is State maintained )	
(2) City or County Highway	Maintenance Official (if bridge is not State maintained)	
(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate	
(4) TDOT Regional Bridge	_	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offici	•	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked
	oridge can be re-opened only after a TDC and they are determined to be structura	OT bridge inspection team checks the substructure ally stable.
CONT	ACT PERSONNEL:	TELEPHONE NUMBER:
COUN	TY MAYOR'S OFFICE	(731) 968-0122
HWY.	CHIEF ADMINISTRATOR'S OFFICE	(731) 968-9201
COUN	TY SHERIFF'S OFFICE	(731) 968-7777
The re	eport shall include the date and time of t propriate, photographs of the bridge and	ection to BridgeWatch scour monitoring system. he inspection, a brief summary of findings and, d stream channel measurements. If significant e copied to Bridge Inspection Headquarters.
COMMENTS		
Suggested	List of Equipment to conduct the Inspec	tion:
Latest Bridg	ge Inspection Report	
Scour POA	Report with the above Checklist	
_	ign Plans, if available	
•	ure with weight	
Plumb bob		
Range Pole		
A 1000 Foot	, ,	ape printed with the following message:
	SAFETY HAZARD KEE	PAWAY

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape