HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 41S61790003 BRIDGE OWNER: HICKMAN COUNTY ROAD NAME: CANE CR RD

CROSSING: CANE CREEK

LATITUDE:: N 35.64862 DEGREES

COUNTY: HICKMAN ROUTE: 00942 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 3.21

LON	IGITUDE: W 87.66022 DEGREES	YEAR BUILT: 1959
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE SPILL THROUGH ABUTI	MENT ON CONCRETE SPREAD FOOTING FOUNDATION
BENTS:	STEEL PILE BENT ON PILE FOUNDA	ATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge is sco	our critical: field review indicates t	hat extensive scour has occurred at bridge foundations. Immediate action
		. No scour countermeasures are installed but they are needed.
		INSPECTION PROCEDURES
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert
	•	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. 0 2. 0 [] - Checl [] - Checl	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or l k pier exposure, if possible, an	n along curb line, both bridge rails and outer edge of bridge deck. its.
[] - Stay a	ty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as lists to stay off of the bridge until such time as the bridge may
-	•	upervisor (if bridge is State maintained)
- -	` '	/ Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 729-2492		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 729-2482		
COUNTY SHERIFF'S OFFICE	(931) 729-6143		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspec	etion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade T	ape printed with the following message:		
SAFETY HAZARD KEEP	PAWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19