HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 460A2970005
BRIDGE OWNER: JOHNSON COUNTY

ROAD NAME: **STAGE RD**CROSSING: **FORGE CREEK**

LATITUDE:: N 36.45303 DEGREES
LONGITUDE: W 81.88010 DEGREES

COUNTY: JOHNSON
ROUTE: 0A302
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.18

LON	IGHODE: W 81.88010 DEGREES	YEAR BUILT: 1978
		TYPE OF SUPERSTRUCTURE -
MAIN SPAN:	CONCRETE - SLAB	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	TEEL PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE SOLID SHAFT PIER ON	ROCK FOUNDATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress ntermeasures are installed but they are needed.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	•	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	<u>heck on a bridge during floods</u>	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
1. C	Check displacement / deflectio	n along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	nts.
[] - Chec	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
[] - Chec	k pier exposure, if possible, ar	nd compare to previous inspection
[] - Revie	w the latest bridge inspection	report versus current field conditions
lf Claavina ia		
	recommended:	
Coun temp	ty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u FDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked
[] - The bridge can be re-opened only after a Tunits and they are determined to be structu	DOT bridge inspection team checks the substructure urally stable.
CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(423) 727-9696
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 727-7851
COUNTY SHERIFF'S OFFICE	(423) 727-7761
as appropriate, photographs of the bridge a	of the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.
Suggested List of Equipment to conduct the Insp	pection:
Latest Bridge Inspection Report	
Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:
SAFETY HAZARD KE	EEP AWAY
A Barricade Tape Dispenser with serrated cutter	

PUBLICATION DATE
17-Apr-19

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone