HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 490A1360001

BRIDGE OWNER: LAUDERDALE COUNTY

ROAD NAME: **SMITH RD**CROSSING: **BRANCH**

LATITUDE:: N 35.87058 DEGREES
LONGITUDE: W 89.44514 DEGREES

COUNTY: LAUDERDALE
ROUTE: 0A136
SPECIAL CASE: 0
COUNTY SEQUENCE: 1

LOG MILE: 0.21 YEAR BUILT: 1975

			12/11/2012// 10/0
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM	OR GIRDER APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FO		
BENTS:	TIMBER PILE BENT ON PILE FOUN		
PIERS:	NOT APPLICABLE		
	NOT 711 1 210/1522		
		SCOUR EVALUATION	
during signif			bridge shall be monitored for distress n poor condition. Significant repairs to the
		- INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	•	•	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
Things to c	heck on a bridge during flood	ls:	
[] - Span	movement - horizontally as v	vell as vertically	
	•	•	e rails and outer edge of bridge deck.
	Check for plumb of piers or be		
	k for embankment erosion		
	k for drift build-up on piers o	r bents	
	• •	and compare to previous insp	ection
		n report versus current field o	
	.	•	
<u>lf Closure is</u>	recommended:		
Coun temp	ity or City Maintenance Perso	nnel. Use Barricade Tape, tra prists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State	e maintained)
	(2) City or County Highw	ay Maintenance Official (if b	ridge is not State maintained)
	(3) Tennessee Highway F	Patrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridg	e Engineer	
	Bridge should remain closed of TDOT bridge inspection team		daylight visual inspection is made

PUBLICATION DATE

17-Apr-19

BRIDGE ID 490A1360001

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route prior to signing the detour route.	e. Any bridge on the selected detour route shall be checked			
	ne bridge can be re-opened only after a TDOT bridge inspection team checks the substructure nits and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(731) 635-3500			
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 635-9251			
COUNTY SHERIFF'S OFFICE	(731) 635-1311			
as appropriate, photographs of the brid	ime of the inspection, a brief summary of findings and, dge and stream channel measurements. If significant I also be copied to Bridge Inspection Headquarters.			
Suggested List of Equipment to conduct the	Inspection:			
Latest Bridge Inspection Report				
Scour POA Report with the above Checklist				
Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow Polyethylene Barr	ricade Tape printed with the following message:			
SAFETY HAZAR	D KEEP AWAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19