## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 550A0070001

BRIDGE OWNER: McNAIRY COUNTY

ROAD NAME: ROWSEY SCHOOL RD

CROSSING: WOODVILLE CREEK

LATITUDE:: N 35.23077 DEGREES

COUNTY: McNAIRY
ROUTE: 01631
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.99
YEAR BUILT: 2013

LON	NGH ODE. W 66.74297 DEGREES	TEAR BOILT. 2013	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Dridge is see	our critical: bridge foundations de	remined to be unstable for calculated scour conditions. Rip-rap protection	
	stalled and is in good condition.	ermined to be dristable for calculated scool conditions. Rip-rap protection	
		INSPECTION PROCEDURES ————————————————————————————————————	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
Things to c	heck on a bridge during floods	•	
_			
	movement - horizontally as w	along curb line, both bridge rails and outer edge of bridge deck.	
	Check for plumb of piers or be		
	k for embankment erosion		
	k for drift build-up on piers or	pents	
	• •	d compare to previous inspection	
		report versus current field conditions	
	3 .	•	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Persor	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway P	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



	ficials in establishing a detour route. Any b ior to signing the detour route.	ridge on the selected detour route shall be checked		
		ge can be re-opened only after a TDOT bridge inspection team checks the substructure d they are determined to be structurally stable.		
<u>co</u>	NTACT PERSONNEL:	TELEPHONE NUMBER:		
co	DUNTY MAYOR'S OFFICE	(731) 645-3472		
ни	VY. CHIEF ADMINISTRATOR'S OFFICE	(731) 645-3651		
co	DUNTY SHERIFF'S OFFICE	(731) 645-1000		
as sco	appropriate, photographs of the bridge and	the inspection, a brief summary of findings and, distream channel measurements. If significant be copied to Bridge Inspection Headquarters.		
Suggest	ed List of Equipment to conduct the Inspec	etion:		
Latest B	ridge Inspection Report			
	OA Report with the above Checklist			
_	esign Plans, if available			
•	asure with weight			
Plumb be				
Range P				
A 1000 F	oot Roll of yellow Polyethylene Barricade 1			
	SAFETY HAZARD KEE	PAWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24