HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 780A3300001

BRIDGE OWNER: SEVIER COUNTY

ROAD NAME: RICHARDSON COVE RD

CROSSING: LITTLE PIGEON RIVER

LATITUDE:: N 35.81560 DEGREES

COUNTY: SEVIER
ROUTE: 0A330
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.01
YEAR BUILT: 1965

LON	NGHODE. W 63.43616 DEGREES	•		TEAR BOILT. 1903
		TYPE OF SUP	ERSTRUCTURE -	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	BEAM OR	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SU	BSTRUCTURE =	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON UNKNOV	N FOUNDATION	
BENTS:	NOT APPLICABLE			
PIERS:	CONCRETE HAMMERHEAD PIER O	N UNKNOWN FO	OUNDATION	
		SCOUR E	/ALUATION =	
	unknown foundations. Risk of scr icant flood events. Monitor bridg			bridge shall be monitored for distress termeasures.
		INSPECTION	PROCEDURES =	
What Initiated the Call-out Inspection		[] Bridg	eWatch Alert	
		[] TDOT	District or Loca	al Maintenance Personnel
		[] THP o	or Local Law Ent	forcement Personnel
		[] Other	:	
[] - Span 1. 0 2. 0 [] - Chec [] - Chec [] - Revis	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a ew the latest bridge inspection	vell as vertical on along curb nts. bents nd compare to	line, both bridge	
<u>If Closure is</u>	recommended:			
Coun temp	nty or City Maintenance Persor	nnel. Use Barı rists to stay o	ricade Tape, traf	eured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (i	f bridge is State	maintained)
	(2) City or County Highwa	ay Maintenand	e Official (if br	idge is not State maintained)
	(3) Tennessee Highway P	atrol and/or lo	ocal law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer		
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	shing a detour route. Any b	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked			
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 				
CONTACT PERSONNE	<u>L:</u>	TELEPHONE NUMBER:			
COUNTY MAYOR'S OF	FICE	(865) 453-6136			
HWY. CHIEF ADMINIS	RATOR'S OFFICE	(865) 453-3452			
COUNTY SHERIFF'S O	FFICE	(865) 453-4668			
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.					
COMMENTS:					
Suggested List of Equip	ment to conduct the Inspec	ction:			
Scour POA Report with t	he above Checklist				
Bridge Design Plans, if a					
Tape measure with weig	ht				
Plumb bob					
Range Pole					
A 1000 Foot Roll of yello		Tape printed with the following message:			
	SAFETY HAZARD KEE	P AWAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24