HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 80S62960001
BRIDGE OWNER: SMITH COUNTY
ROAD NAME: ROME RD
CROSSING: WILBURN CREEK

LATITUDE:: N 36.32865 DEGREES
LONGITUDE: W 86.06262 DEGREES

COUNTY: SMITH
ROUTE: 01085
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.31
YEAR BUILT: 1955

		TYPE OF	SUPERSTRUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF		APPR. SPAN:	NOT APPLICABLE
			F SUBSTRUCTURE -	
	CONCRETE SPILL THROUGH ABUT	MENT ON C	CONCRETE PILE FOUND	ATION
BENTS:	NOT APPLICABLE			
PIERS:	CONCRETE COLUMNS WITH SOLID	WEB WAL	L (DUMB BELL) ON UNK	NOWN FOUNDATION
		SCOL	JR EVALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.
		INSPECT	ION PROCEDURES -	
What Initiat	ed the Call-out Inspection?	ſ 1 Br	ridgeWatch Alert	
Triat miliatos ino Gail Gai mopositori.			_	I Maintenance Personnel
				orcement Personnel
		·		
Things to c	heck on a bridge during floods	<u>::</u>		
	movement - horizontally as we		ically	
	•		•	e rails and outer edge of bridge deck.
	Check for plumb of piers or ber	_	arb iiric, botir briage	rans and outer eage of bridge deck.
	k for embankment erosion	113.		
	k for drift build-up on piers or l	hents		
	k pier exposure, if possible, an		re to previous inspe	ection
	ew the latest bridge inspection	-	•	
[] - Kevic	w the latest bridge mapeetion	report ve		Similaris
lf Closure is	recommended:			
Coun temp	nty or City Maintenance Person	nel. Use	Barricade Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	uperviso	r (if bridge is State	maintained)
	(2) City or County Highway	y Mainter	nance Official (if bri	idge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/	or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	•	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made FDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	detour route. Any bridge on t	et maintenance or local highway maintenance the selected detour route shall be checked			
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.				
CONTACT PERSONNEL:		TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE		(615) 735-2294			
HWY. CHIEF ADMINISTRATOR'S	3 OFFICE	(615) 683-3326			
COUNTY SHERIFF'S OFFICE		(615) 735-2626			
The report shall include th as appropriate, photograp	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS:					
Suggested List of Equipment to	conduct the Inspection:				
Latest Bridge Inspection Report	:				
Scour POA Report with the above	ve Checklist				
Bridge Design Plans, if available	;				
Tape measure with weight					
Plumb bob					
Range Pole					
A 1000 Foot Roll of yellow Polye	• • • •	ed with the following message:			
SAF	FETY HAZARD KEEP AWAY				

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24