HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 920A5660001
BRIDGE OWNER: WEAKLEY COUNTY
ROAD NAME: TUMBLING CR RD
CROSSING: TUMBLING CREEK

LATITUDE:: N 36.23778 DEGREES LONGITUDE: W 88.54389 DEGREES

COUNTY: WEAKLEY
ROUTE: 0A566
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.23
YEAR BUILT: 1994

20.	10.10 00.0 4000 DIONELLO			12/11C 501E11. 1004
		TYPE OF SUPE	ERSTRUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUE	STRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOW	N FOUNDATION	
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
			ALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress ntermeasures.
		INSPECTION I	PROCEDURES =	
What Initiated the Call-out Inspection?		[] Bridge	Watch Alert	
	·			al Maintenance Personnel
				forcement Personnel
1. C 2. C [] - Chec	movement - horizontally as w Check displacement / deflectio Check for plumb of piers or bea k for embankment erosion k for drift build-up on piers or	n along curb l nts.	•	e rails and outer edge of bridge deck.
	k pier exposure, if possible, ar		nrevious insn	ection
	ew the latest bridge inspection	-	-	
[]	on the latest Shage mepochen	Topon voicus	o dan one nord d	
<u>lf Closure is</u>	recommended:			
Coun temp	nty or City Maintenance Persor	nnel. Use Barr ists to stay of	icade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if	bridge is State	e maintained)
	(2) City or County Highwa	y Maintenanc	e Official (if b	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or lo	cal law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked				
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.				
CONTACT PERSONNEL:	TELEPHONE NUMBER:				
COUNTY MAYOR'S OFFICE	(731) 364-5413				
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 364-2284				
COUNTY SHERIFF'S OFFICE	(731) 364-5454				
The report shall include the date a as appropriate, photographs of the	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS:					
Suggested List of Equipment to conduct	t the Inspection:				
Latest Bridge Inspection Report					
Scour POA Report with the above Check	dist				
Bridge Design Plans, if available					
Tape measure with weight					
Plumb bob					
Range Pole					
A 1000 Foot Roll of yellow Polyethylene	Barricade Tape printed with the following message:				
SAFETY HA	ZARD KEEP AWAY				

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24