HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 020A3740003
BRIDGE OWNER: BEDFORD COUNTY

ROAD NAME: **WHEEL RD**CROSSING: **DUCK RIVER**

LATITUDE:: N 35.55288 DEGREES
LONGITUDE: W 86.58210 DEGREES

COUNTY: BEDFORD
ROUTE: 0A374
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.86
YEAR BUILT: 1960

TYPE OF SUPERSTRUCTURE MAIN SPAN-STEEL - STRINGER/MULTI-BEAM OR GIRDER APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION BENTS: **NOT APPLICABLE** PIERS: CONCRETE SOLID SHAFT PIER ON CONCRETE SPREAD FOOTING FOUNDATION SCOUR EVALUATION Bridge has unknown foundations. Risk of scour cannot be determined. The bridge shall be monitored for distress during significant flood events. Monitor bridge in lieu of installing scour countermeasures. **INSPECTION PROCEDURES** [] BridgeWatch Alert What Initiated the Call-out Inspection? [1 TDOT District or Local Maintenance Personnel [] THP or Local Law Enforcement Personnel [] Other: Things to check on a bridge during floods: [] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [] - Check for embankment erosion [] - Check for drift build-up on piers or bents [] - Check pier exposure, if possible, and compare to previous inspection [] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. [] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained) (2) City or County Highway Maintenance Official (if bridge is not State maintained) (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate (4) TDOT Regional Bridge Engineer [] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made

PUBLICATION DATE

by a TDOT bridge inspection team.

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in esta		State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked	
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSON	INEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S	OFFICE	(931) 684-7944	
COUNTY SHERIFF'S OFFICE		(931) 836-3232	
HWY. CHIEF ADMII	NISTRATOR'S OFFICE	(931) 684-4651	
The report shall as appropriate,	include the date and time on the photographs of the bridge a	spection to BridgeWatch scour monitoring system. of the inspection, a brief summary of findings and, and stream channel measurements. If significant o be copied to Bridge Inspection Headquarters.	
COMMENTS:			
Suggested List of Equ	uipment to conduct the Insp	pection:	
Latest Bridge Inspect	ion Report		
Scour POA Report wit	th the above Checklist		
Bridge Design Plans,	if available		
Tape measure with we	eight		
Plumb bob			
Range Pole			
A 1000 Foot Roll of ye	llow Polyethylene Barricade	e Tape printed with the following message:	
	SAFETY HAZARD KE	EEP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24