## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 120A2990003

BRIDGE OWNER: CHESTER COUNTY

ROAD NAME: EMMERSON RD

CROSSING: LITTLE SUGAR CREEK

LATITUDE:: N 35.35525 DEGREES

LONGITUDE: W 88.73672 DEGREES

COUNTY: CHESTER
ROUTE: 0A299
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.50
YEAR BUILT: 1995

		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBED CAR ON TIMBED BILL EQUI		
BENTS:			
PIERS:	NOT APPLICABLE	SATION	
TILINO.	NOT ALL EIGABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiat	ted the Call-out Inspection?	[ ] BridgeWatch Alert	
•		[ ] TDOT District or Local Maintenance Personnel	
		THP or Local Law Enforcement Personnel	
		[ ] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
[ ] - Span	movement - horizontally as we	ell as vertically	
		n along curb line, both bridge rails and outer edge of bridge deck.	
	Check for plumb of piers or ber		
	k for embankment erosion		
[ ] - Check for drift build-up on piers or bents			
	• •	nd compare to previous inspection	
Review the latest bridge inspection report versus current field conditions			
	geepee		
<u>If Closure is</u>	recommended:		
Cour	] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.		
[ ] - Cont	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	<ul> <li>The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.</li> </ul>		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



<ul> <li>The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route.</li> </ul>	District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 989-5672		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 989-7311		
COUNTY SHERIFF'S OFFICE	(731) 989-2787		
- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	an uninted with the following managers.		
A 1000 Foot Roll of yellow Polyethylene Barricade Tap SAFETY HAZARD KEEP			
SAFETT HAZARD REEP /	311/31		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24