## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 230A4260003 BRIDGE OWNER: DYER COUNTY ROAD NAME: PEACH ORCHARD RD CROSSING: BRANCH

LATITUDE:: N 35.89206 DEGREES LONGITUDE: W 80 30742 DEGREES

COUNTY: DYER ROUTE: 0A426 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.69 VEAR BILLT: 1070

| LON  | NGHODE: W 69.30742 DEGREES                                    | I LAN BOILT. 1970  |
|--|---|--|
|  |   | TYPE OF SUPERSTRUCTURE   |
| MAIN SPAN:   | CONCRETE - CHANNEL BEAM                                       | APPR. SPAN: NOT APPLICABLE   |
|  |   | TYPE OF SUBSTRUCTURE   |
| ABUTMENTS:   | TIMBER CAP ON TIMBER PILE FOU                                 | INDATION   |
| BENTS:   | TIMBER PILE BENT ON PILE FOUN                                 | DATION   |
| PIERS:   | NOT APPLICABLE  |  |
|  |   | SCOUR EVALUATION   |
| Bridge is so   | our critical: bridge foundations de                           | etermined to be unstable for calculated scour conditions. Monitor bridge in  |
|  | ling scour countermeasures.                                   | etermined to be unstable for calculated scour conditions. Monitor bridge in  |
|  |   | INSPECTION PROCEDURES -  |
| What Initiated the Call-out Inspection?  |   | [ ] BridgeWatch Alert  |
|  |   | [ ] TDOT District or Local Maintenance Personnel   |
|  |   | [ ] THP or Local Law Enforcement Personnel   |
|  |   | [ ] Other:   |
|  |   |  |
| Things to c  | heck on a bridge during floods                                | <u>s:</u>  |
| [ ] - Span   | movement - horizontally as w                                  | ell as vertically  |
|  |   | n along curb line, both bridge rails and outer edge of bridge deck.  |
| 2. (   | Check for plumb of piers or be                                | nts.   |
| [ ] - Chec   | k for embankment erosion                                      |  |
| [ ] - Chec   | k for drift build-up on piers or                              | bents  |
| [ ] - Chec   | k pier exposure, if possible, a                               | nd compare to previous inspection  |
| [ ] - Review the latest bridge inspection report versus current field conditions |   |  |
|  |   |  |
|  |   |  |
| <u>If Closure is</u>   | <u>recommended:</u>   |  |
| Cour<br>temp   | nty or City Maintenance Persor                                | cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may |
| [ ] - Conta  | act: (1) District Maintenance S                               | Supervisor ( if bridge is State maintained )   |
|  | (2) City or County Highwa                                     | y Maintenance Official ( if bridge is not State maintained )   |
|  | (3) Tennessee Highway P                                       | atrol and/or local law enforcement Officers as appropriate   |
|  | (4) TDOT Regional Bridge                                      | Engineer   |
|  | Bridge should remain closed u<br>TDOT bridge inspection team. | ntil the water recedes and a daylight visual inspection is made  |

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



|  | h State District maintenance or local highway maintenance<br>ny bridge on the selected detour route shall be checked  |  |  |
|--|---|--|--|
|  | - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.   |  |  |
| CONTACT PERSONNEL:   | TELEPHONE NUMBER:   |  |  |
| COUNTY MAYOR'S OFFICE  | (731) 286-7800  |  |  |
| HWY. CHIEF ADMINISTRATOR'S OFFICE  | (731) 286-7838  |  |  |
| COUNTY SHERIFF'S OFFICE  | (731) 285-2802  |  |  |
| The report shall include the date and time as appropriate, photographs of the bridge | <ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.</li> <li>The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.</li> </ul> |  |  |
| COMMENTS:  |   |  |  |
| Suggested List of Equipment to conduct the Inc                                       | spection:   |  |  |
| Scour POA Report with the above Checklist  |   |  |  |
| Bridge Design Plans, if available  |   |  |  |
| Tape measure with weight   |   |  |  |
| Plumb bob  |   |  |  |
| Range Pole   |   |  |  |
| A 1000 Foot Roll of yellow Polyethylene Barrica                                      |   |  |  |
| SAFFTY HAZARD I  | KEEP AWAY   |  |  |

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24