HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 270A1610003

BRIDGE OWNER: GIBSON COUNTY

ROAD NAME: BOHAM RD

CROSSING: BR RUTHERFORD FORK OBION
LATITUDE:: N 36.07783 DEGREES
LONGITUDE: W 88.94306 DEGREES

ROUTE: 0A161
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.25
YEAR BUILT: 1992

COUNTY: GIBSON

		TYPE OF CUREPSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	TYPE OF SUPERSTRUCTURE APPR. SPAN: NOT APPLICABLE
MAIN SPAN.	CONCRETE - CHANNEL BEAM	AFFR. SPAN. NOI APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	INDATION
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress
during signii	icant nood events. Monitor bridge	e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	check on a bridge during floods	e·
•		
	movement - horizontally as w	•
	<u>.</u>	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	nts.
	k for embankment erosion	h anda
	ck for drift build-up on piers or	
		nd compare to previous inspection
[] - Revie	w the latest bridge inspection	report versus current field conditions
<u>If Closure is</u>	s recommended:	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked		
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure nd they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 855-7611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684		
COUNTY SHERIFF'S OFFICE	(731) 855-1121		
The report shall include the date and time of as appropriate, photographs of the bridge a	Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Insp	pection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricad	e Tape printed with the following message:		
SAFETY HAZARD KE	EEP AWAY		

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

PUBLICATION DATE
17-Apr-19

A roll of Duct Tape

BRIDGE ID 270A1610003