HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 33022250001
BRIDGE OWNER: HAMILTON COUNTY
ROAD NAME: ROCK CREEK RD
CROSSING: HODGETOWN BRANCH
LATITUDE:: N 35.38163 DEGREES
LONGITUDE: W 85.10315 DEGREES

COUNTY: HAMILTON
ROUTE: 05709
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.33
YEAR BUILT: 1930

		TYPE OF SUPERSTRUCTURE =			
MAIN SPAN:	CONCRETE - SLAB		NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE =			
ABUTMENTS:	MASONRY OR CONCRETE BLOCK A	ABUTMENTS ON UNKNOWN FOUNI	DATION		
BENTS:	NOT APPLICABLE				
PIERS:	MASONRY OR CONCRETE BLOCK F	PIER ON UNKNOWN FOUNDATION			
		SCOUR EVALUATION -			
	unknown foundations. Risk of sco iicant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.		
		INSPECTION PROCEDURES =			
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert			
		[] TDOT District or Loca	al Maintenance Personnel		
		[] THP or Local Law Enf	forcement Personnel		
		[] Other:			
Things to c	<u>heck on a bridge during floods</u>	<u>:</u>			
[] - Span	movement - horizontally as we	ell as vertically			
1. 0	Check displacement / deflection	n along curb line, both bridge	e rails and outer edge of bridge deck.		
	Check for plumb of piers or ben	nts.			
] - Check for embankment erosion				
	k for drift build-up on piers or l				
[] - Check pier exposure, if possible, and compare to previous inspection					
[] - Review the latest bridge inspection report versus current field conditions					
<u>lf Closure is</u>	recommended:				
Coun temp] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.				
[] - Conta	act: (1) District Maintenance So	upervisor (if bridge is State	maintained)		
	(2) City or County Highway	y Maintenance Official (if br	idge is not State maintained)		
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate		
	(4) TDOT Regional Bridge	Engineer			
	The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 209-6100		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 855-6106		
PUBLIC WORKS DIRECTOR	(423) 209-7899		
COUNTY SHERIFF'S OFFICE	(423) 209-7000		
[] - Summarize and submit findings from the inspective The report shall include the date and time of the as appropriate, photographs of the bridge and secouring has occurred, the report shall also be COMMENTS:	e inspection, a brief summary of findings and, stream channel measurements. If significant copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspection	on:		
	<u>011.</u>		
Latest Bridge Inspection Report Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
SAFETY HAZARD KEEP	AWAY		
A Barricade Tape Dispenser with serrated cutter			

PUBLICATION DATE

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

07-Nov-24