## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 330C5960001

BRIDGE OWNER: CITY OF CHATTANOOGA

ROAD NAME: **BOY SCOUT RD**CROSSING: **PITTS BRANCH** 

LATITUDE:: N 35.18332 DEGREES LONGITUDE: W 85.25025 DEGREES

COUNTY: HAMILTON
ROUTE: 0C596
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.22
YEAR BUILT: 1950

		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION	
		SCOUR EVALUATION =	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES =	
What Initiat	ed the Call-out Inspection?	[ ] BridgeWatch Alert	
			al Maintenance Personnel
		[ ] THP or Local Law En	
[ ] - Span 1. 0 2. 0 [ ] - Chec [ ] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous inspe	
<u>If Closure is</u>	recommended:		
Cour temp	] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.		
[ ] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)			
	(2) City or County Highwa	y Maintenance Official ( if br	ridge is not State maintained )
	, , ,	•	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	- -
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



<ul> <li>The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.</li> </ul>			
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(423) 757-5152		
CITY ENGINEER'S OFFICE	(423) 757-5115		
POLICE OFFICE	(423) 698-9744		
PUBLIC WORKS DIRECTOR	(423) 757-5152		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and,         as appropriate, photographs of the bridge and stream channel measurements. If significant         scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.</li> </ul> <li>COMMENTS:</li>			
Suggested List of Equipment to conduct the Inspecti	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AVVAT		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24