HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 330D5020001

BRIDGE OWNER: CITY OF SODDY-DAISY

ROAD NAME: **DEPOT ST**

CROSSING: LITTLE SODDY CREEK
LATITUDE:: N 35.28868 DEGREES
LONGITUDE: W 85.16502 DEGREES

COUNTY: HAMILTON
ROUTE: 0D502
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.91

LON	NGITUDE: W 85.16502 DEGREES	•	YEAR BUILT: 1935
		TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)	RT (INCLUDES APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	MASONRY OR CONCRETE BLOCK	ABUTMENTS ON UNKNOWN FOUND	DATION
BENTS:	NOT APPLICABLE		
PIERS:	MASONRY OR CONCRETE BLOCK	PIER ON UNKNOWN FOUNDATION	
		SCOUR EVALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
		[] TDOT District or Loca	Il Maintenance Personnel
		[] THP or Local Law Enf	orcement Personnel
		[] Other:	
[] - Span 1. C 2. C [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as w Check displacement / deflectio Check for plumb of piers or bei k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridge nts. bents nd compare to previous inspe	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, traf rists to stay off of the bridge u	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	maintained)	
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offici		e District maintenance or local highway maintenance idge on the selected detour route shall be checked	
[] - The bunits	he bridge can be re-opened only after a TDOT bridge inspection team checks the substructure nits and they are determined to be structurally stable.		
CONT	ACT PERSONNEL:	TELEPHONE NUMBER:	
CITY	MAYOR'S OFFICE	(423) 332-5323	
POLIC	E OFFICE	(423) 332-3577	
PUBL	C WORKS DIRECTOR	(423) 332-5323	
The re	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS			
	List of Equipment to conduct the Inspect	ion:	
	ge Inspection Report		
	Report with the above Checklist ign Plans, if available		
•	ure with weight		
Plumb bob			
Range Pole			
A 1000 Foo	t Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:	
	SVEETA HVAVDU REED	AWAY	

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape