## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 330E3830001

BRIDGE OWNER: CITY OF CHATTANOOGA

ROAD NAME: **DAVIDSON RD**CROSSING: **MACKEY BRANCH** 

LATITUDE:: N 35.00365 DEGREES
LONGITUDE: W 85.17018 DEGREES

COUNTY: HAMILTON
ROUTE: 05784
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.01

LONGITUDE: W 85.17018 DEGREES YEAR BUILT: 1981 TYPE OF SUPERSTRUCTURE PRESTRESSED CONCRETE - BOX BEAM OR APPR. SPAN: NOT APPLICABLE MAIN SPAN-**GIRDERS - MULTIPLE**  TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE SPREAD FOOTING FOUNDATION BENTS: **NOT APPLICABLE** PIERS: **NOT APPLICABLE SCOUR EVALUATION** Bridge has unknown foundations. Risk of scour cannot be determined. The bridge shall be monitored for distress during significant flood events. Monitor bridge in lieu of installing scour countermeasures. INSPECTION PROCEDURES What Initiated the Call-out Inspection? [ ] BridgeWatch Alert [ ] TDOT District or Local Maintenance Personnel [ 1 THP or Local Law Enforcement Personnel [ ] Other: Things to check on a bridge during floods: [ ] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [ ] - Check for embankment erosion [ ] - Check for drift build-up on piers or bents [ ] - Check pier exposure, if possible, and compare to previous inspection [ ] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [ ] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. [ ] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained) (2) City or County Highway Maintenance Official (if bridge is not State maintained) (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate (4) TDOT Regional Bridge Engineer

## **PUBLICATION DATE**

by a TDOT bridge inspection team.

[ ] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked
[ ] - The bridge can be re-opened only after a TI units and they are determined to be structu	DOT bridge inspection team checks the substructure irally stable.
CONTACT PERSONNEL:	TELEPHONE NUMBER:
CITY MAYOR'S OFFICE	(423) 757-5152
CITY ENGINEER'S OFFICE	(423) 757-5115
POLICE OFFICE	(423) 698-9744
PUBLIC WORKS DIRECTOR	(423) 757-5152
as appropriate, photographs of the bridge a	f the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.
Suggested List of Equipment to conduct the Inspection Report	ection:
Latest Bridge Inspection Report Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:
SAFETY HAZARD KE	EP AWAY
A Barricade Tape Dispenser with serrated cutter	

**PUBLICATION DATE** 

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

07-Nov-24