HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 33SR0290013

BRIDGE OWNER: CITY OF SODDY-DAISY

ROAD NAME: DAYTON PK S

CROSSING: CHICKAMAUGA CREEK
LATITUDE:: N 35.22168 DEGREES
LONGITUDE: W 85.22160 DEGREES

COUNTY: HAMILTON
ROUTE: 02162
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.76
YEAR BUILT: 1983

		TYPE OF SUPER	STRUCTURE -		
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE	NUOUS -	APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBS	TRUCTURE -		
ABUTMENTS:	ENTS: CONCRETE STUB ABUTMENT ON STEEL PILE FOUNDATION NOT APPLICABLE				
BENTS:					
PIERS:	CONCRETE HAMMERHEAD PIER ON CONCRETE SPREAD FOOTING FOUNDATION				
		SCOUR EVA	LUATION -		
•	our critical; bridge foundations de ing scour countermeasures.			culated scour conditions. Monitor bridge in	
		INSPECTION PF	ROCEDURES -		
What Initiated the Call-out Inspection?		[] BridgeV	Watch Alert		
		[] TDOT District or Local Maintenance Personnel			
		[] THP or	Local Law Enf	orcement Personnel	
		[] Other:			
[] - Span	heck on a bridge during floods movement - horizontally as w Check displacement / deflectio	ell as vertically		e rails and outer edge of bridge deck.	
	Check for plumb of piers or be	_			
[] - Chec	k for embankment erosion				
[] - Chec	k for drift build-up on piers or	bents			
[] - Chec	k pier exposure, if possible, ar	nd compare to	previous inspe	ection	
[] - Revie	w the latest bridge inspection	report versus	current field co	onditions	
<u>If Closure is</u>	recommended:				
Coun temp	ty or City Maintenance Persor	nnel. Use Barrio	ade Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	Supervisor (if b	oridge is State	maintained)	
	(2) City or County Highwa	y Maintenance	Official (if bri	idge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or loc	al law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	e Engineer			
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offici		e District maintenance or local highway maintenance idge on the selected detour route shall be checked			
[] - The bunits	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.				
CONT	ACT PERSONNEL:	TELEPHONE NUMBER:			
CITY	MAYOR'S OFFICE	(423) 332-5323			
POLIC	E OFFICE	(423) 332-3577			
PUBL	C WORKS DIRECTOR	(423) 332-5323			
The re	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS					
	List of Equipment to conduct the Inspect	ion:			
	ge Inspection Report				
	Report with the above Checklist ign Plans, if available				
•	ure with weight				
Plumb bob					
Range Pole					
A 1000 Foo	t Roll of yellow Polyethylene Barricade Ta	ape printed with the following message:			
	SVEETA HVAVDU REED	AWAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24