HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 33SR0290029

BRIDGE OWNER: CITY OF SODDY-DAISY

ROAD NAME: DAYTON PK

CROSSING: BIG SODDY CREEK OVERFLOW
LATITUDE:: N 35.29720 DEGREES
LONGITUDE: W 85.14873 DEGREES

COUNTY: HAMILTON
ROUTE: 03634
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.75
YEAR BUILT: 1932

		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON TIMBER PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE COLUMNS WITH SOLI	D WEB WALL (DUMB BELL) ON TIMBER PILE FOUNDATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	rell as vertically on along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Cour temp] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.	
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	Bridge should remain closed บ TDOT bridge inspection team.	intil the water recedes and a daylight visual inspection is made

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	m will work with State District maintenance or local highway maintenance detour route. Any bridge on the selected detour route shall be checked ir route.		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(423) 332-5323		
POLICE OFFICE	(423) 332-3577		
PUBLIC WORKS DIRECTOR	(423) 332-5323		
The report shall include to as appropriate, photogra	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment t	conduct the Inspection:		
Latest Bridge Inspection Repo	:		
Scour POA Report with the abo	ve Checklist		
Bridge Design Plans, if availab)		
Tape measure with weight			
Plumb bob			
Range Pole			
	ethylene Barricade Tape printed with the following message:		
SA	FETY HAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

07-Nov-24

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)