## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 35\$80810011

BRIDGE OWNER: HARDEMAN COUNTY
ROAD NAME: POWELL CHAPEL RD
CROSSING: SKIPPER CREEK

LATITUDE:: N 35.13847 DEGREES LONGITUDE: W 88.81011 DEGREES

COUNTY: HARDEMAN
ROUTE: 00869
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 6.96
YEAR BUILT: 1951

LOI	NGHODE. W 66.61011 DEGREE	TEAN BOILT. 1931
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	CONCRETE PILE FOUNDATION
BENTS: CONCRETE PILE BENT ON PILE FOUNDATION		DUNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge is see	our critical: bridge foundations de	etermined to be unstable for calculated scour conditions. No scour
-	sures are installed but they are r	
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
[ ] - Span	movement - horizontally as w	vell as vertically
	•	on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
[ ] - Chec	k for embankment erosion	
[ ] - Chec	k for drift build-up on piers or	bents
	• •	nd compare to previous inspection
		report versus current field conditions
	<b>.</b>	·
<u>If Closure is</u>	recommended:	
Cour temp	nty or City Maintenance Persoi	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[ ] - Cont	Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	ay Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



<ul> <li>The bridge inspection team will work with State officials in establishing a detour route. Any bridge prior to signing the detour route.</li> </ul>	District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 658-3266		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 658-5102		
COUNTY SHERIFF'S OFFICE	(731) 658-3971		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and,         as appropriate, photographs of the bridge and stream channel measurements. If significant         scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.</li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>n:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tap			
SAFETY HAZARD KEEP A	WAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24