HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 410A3480001
BRIDGE OWNER: HICKMAN COUNTY
ROAD NAME: DODD HOLLOW RD
CROSSING: PINEY RIVER

LATITUDE:: N 35.84095 DEGREES LONGITUDE: W 87.53555 DEGREES

COUNTY: HICKMAN
ROUTE: 0A385
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.96
YEAR BUILT: 1968

		TYPE OF SUPERSTRUCTURE =		
MAIN SPAN:	CONCRETE CONTINUOUS - TEE BEA		NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE =		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S			
BENTS:	NOT APPLICABLE			
PIERS:	CONCRETE HAMMERHEAD PIER ON	CONCRETE SPREAD FOOTING FO	DUNDATION	
		SCOUR EVALUATION =		
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.	
		INSPECTION PROCEDURES =		
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert		
		[] TDOT District or Loca	al Maintenance Personnel	
		[] THP or Local Law Enf	forcement Personnel	
		[] Other:		
Things to c	<u>heck on a bridge during floods</u>	<u>.</u>		
[] - Span	movement - horizontally as we	ll as vertically		
1. (Check displacement / deflection	along curb line, both bridge	e rails and outer edge of bridge deck.	
	Check for plumb of piers or ben	ts.		
	k for embankment erosion			
	k for drift build-up on piers or b			
	k pier exposure, if possible, an	· · · · · · · · · · · · · · · · · · ·		
[] - Revie	ew the latest bridge inspection	report versus current field c	onditions	
<u>If Closure is</u>	recommended:			
Cour temp	 Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. 			
[] - Cont	act: (1) District Maintenance So	upervisor (if bridge is State	maintained)	
	(2) City or County Highway	Maintenance Official (if br	idge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
	The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	hing a detour route. Any brid	e District maintenance or local highway maintenance dge on the selected detour route shall be checked	
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL	<u>:</u>	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFF	ICE	(931) 729-2492	
HWY. CHIEF ADMINIST	RATOR'S OFFICE	(931) 729-2482	
COUNTY SHERIFF'S OF	FICE	(931) 729-6143	
The report shall inc as appropriate, pho	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipn	nent to conduct the Inspection	on:	
Latest Bridge Inspection	Report		
Scour POA Report with th	e above Checklist		
Bridge Design Plans, if av	<i>r</i> ailable		
Tape measure with weigh	t		
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellov		pe printed with the following message:	
	SAFETY HAZARD KEEP	AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24