HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 440A1390001 BRIDGE OWNER: JACKSON COUNTY ROAD NAME: SPRING CREEK RD CROSSING: DODSON CREEK

COUNTY: JACKSON ROUTE: 0A139 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	.TITUDE:: N 36.32215 DEGREE IGITUDE: W 85.51166 DEGREE		
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE CONTINUOUS - CULV FRAME CULVERTS)	ERT (INCLUDES APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE BOX TYPE ON CONCI	ETE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	PIER WALL FOR CONCRETE BOX	ON CONCRETE SPREAD FOOTING FOUNDATION	
		SCOUR EVALUATION	
event. Deter		s have been installed to reduce the risk of bridge failure during a flood riprap should be reported to TDOT for assessment. Monitor bridge in lieu	
		INSPECTION PROCEDURES ————————————————————————————————————	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
[] - Span 1. C 2. C [] - Chec [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers o k pier exposure, if possible, a	vell as vertically on along curb line, both bridge rails and outer edge of bridge deck. ents.	
lf Closure is	recommended:		
Coun temp	ity or City Maintenance Perso	ncross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.	
[] - Conta	nct: (1) District Maintenance Supervisor (if bridge is State maintained)		
	(2) City or County Highway Maintenance Official (if bridge is not State maintained)		
	(3) Tennessee Highway I	Patrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridg	e Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure nd they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 268-9888		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 268-9914		
COUNTY SHERIFF'S OFFICE	(931) 268-6226		
as appropriate, photographs of the bridge an	the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Inspe	ction:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:		
SAFETY HAZARD KEE	P AWAY		
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)