## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 47024220001 COUNTY: KNOX
BRIDGE OWNER: KNOX COUNTY ROUTE: 02422
ROAD NAME: EVERETT RD SPECIAL CASE: 0
CROSSING: GRABLE CREEK COUNTY SEQUENCE: 1
LATITUDE:: N 35.88748 DEGREES LOG MILE: 0.78

LATITUDE:: N 35.88748 DEGREES
LONGITUDE: W 84.24333 DEGREES

LON	IGITUDE: W 84.24333 DEGREE	YEAR BUILT: 1930
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)	ERT (INCLUDES APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE BOX TYPE ON CONCR	ETE SPREAD FOOTING FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	PIER WALL FOR CONCRETE BOX	ON CONCRETE SPREAD FOOTING FOUNDATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
1. C 2. C [ ] - Chec [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	on along curb line, both bridge rails and outer edge of bridge deck. onts.
f Closure is	recommended:	
Coun temp	ty or City Maintenance Perso	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
[ ] - Conta	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )
	(2) City or County Highwa	ay Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	Bridge should remain closed u TDOT bridge inspection team.	Intil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any br prior to signing the detour route.	ridge on the selected detour route shall be checked		
[ ]		ge can be re-opened only after a TDOT bridge inspection team checks the substructure I they are determined to be structurally stable.		
	CONTACT PERSONNEL:	TELEPHONE NUMBER:		
	COUNTY MAYOR'S OFFICE	(865) 215-2005		
	HWY. CHIEF ADMINISTRATOR'S OFFICE	(865) 215-5800		
	COUNTY SHERIFF'S OFFICE	(865) 215-2432		
COM	The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be MENTS:	e copied to Bridge Inspection Headquarters.		
Sug	gested List of Equipment to conduct the Inspect	tion:		
Late	est Bridge Inspection Report			
Sco	ur POA Report with the above Checklist			
Brid	lge Design Plans, if available			
Tape	e measure with weight			
Plun	nb bob			
7	ge Pole			
A 10	000 Foot Roll of yellow Polyethylene Barricade T	ape printed with the following message:		
	SAFETY HAZARD KEEP	ΡΑΨΑΥ		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)