## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 490A1170003

BRIDGE OWNER: LAUDERDALE COUNTY

ROAD NAME: BARR RD CROSSING: BRANCH

LATITUDE:: N 35.84336 DEGREES
LONGITUDE: W 89.68842 DEGREES

COUNTY: LAUDERDALE
ROUTE: 0A117
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.75

LOG MILE: 3.75 YEAR BUILT: 2002

		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM (	R GIRDER APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FO	NDATION	
BENTS:	TIMBER COLUMN BENT ON PILE F	DUNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION ————————————————————————————————————	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	•	[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
<u>If Closure is</u>	recommended:		
Cour temp	nty or City Maintenance Perso	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
_		Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway F	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	<ul> <li>The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.</li> </ul>		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked	
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 635-3500	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 635-9251	
COUNTY SHERIFF'S OFFICE	(731) 635-1311	
The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also b	e copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspec	tion:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade T		
SAFETY HAZARD KEEP	PAWAY	
A Barricade Tape Dispenser with serrated cutter		

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

A roll of Duct Tape